## **FAASTeam presents:**

## **Intentional and Unintentional Flight in Icing Conditions**

Mr. Kurt Blankenship is NASA Glenn Research Center's Lead Icing Research Test Pilot. Spend the morning with Kurt while he reviews aircraft icing from the operational perspectives. This seminar will provide pilots with information they can use when planning to fly in icing conditions or confronted with inadvertent icing. Emphasis will focus on planning for intentional flight and avoidance, detection and exit for unintentional flight in these conditions. Kurt will review the effects of ice accretion on performance and handling, Supercooled Large Droplet (SLD) icing, and provide general guidance on recovering from icing-induced conditions, such as wing and tailplane stalls. Imagery, videos, and interactive graphics will be used to provide pilots with visual information that will aid in their identification of different kinds of icing and accretion levels.

Topic OutlineBasic icing physicslcing definitions and terminologyAerodynamic effects of airborne icingAirborne icing weather patternsFlight planning and in-flight icing informationOperation of de- and anti-ice equipmentTechniques for dealing with Inadvertent Icing Conditions

**Directions:** Located in the main terminal building in the west

concourse near gate 5.

**Event Details** 

Sat, Jan 9, 2016 - 10:00 EST Cleveland's Burke Lakefront Airport Terminal Building

1501 North Marginal Road Gate 5

Cleveland, OH 44114



Contact: ROBERT P. HARTIGAN (216) 236-8892

robert.hartigan@aviagogy.com

Select #: GL2566362

Lead Representative ROBERT P. HARTIGAN

## A message from the National FAASTeam Manager

Invite a fellow pilot to the next WINGS Safety Seminar in your area. Sign up for the FAA's safety services at www.FAASafety.gov!

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.